

~~TOP SECRET~~
~~TOP SECRET~~

2	4
3	5
3	5

280420Z 28 NOV 60

DIRECTOR

[REDACTED] 25X1A

OPS (1,2,3,4)

S/C (5)

RR

TOR: 0500Z 28 NOV 60

OPERATIONAL IMMEDIATE

OPERATIONAL IMMEDIATE

IN 37738

25X1A

25X1A

[REDACTED]

[REDACTED]

25X1A

A. POST FLIGHT INSPECTION OF [REDACTED] REVEALED VACUUM

SOLENOID MALFUNCTION. UNABLE TO DETERMINE TIME OF OCCURANCE.

25X1A B. [REDACTED] NEGATIVE SHIPPED TO [REDACTED] IMMEDIATELY AFTER 25X1A

PROCESSING. DUP POSITIVE LATER DESTROYED BY FAULTY PRINTER.

AT THIS STATION. [REDACTED] CANNOT BE PREPARED 25X1A

UNLESS NEGATIVE OR A DUP POSITIVE SENT TO [REDACTED] PLEASE ADVISE. 25X1A

IF YOU REQUIRE ADDITIONAL INFORMATION TO ACCOMPLISH REPORTS

OR IF A COPY OF TAKE WILL BE RETURNED TO [REDACTED] 25X1A

C. STEPS BEING TAKEN TO REPAIR PRINTER. WILL ADVISE.

D. BOTH ARTICLES IN COMMISSION AT THIS TIME. COMPLETE

SECTION ONE [REDACTED] WILL BE SUBMITTED 28 NOV.

END OF MESSAGE

25X1A

25X1A
28 Aug 60

~~TOP SECRET~~